audiolab

Model:	9000A
Version:	V1.78
Issue date:	27th Oct 2023
Type:	Public

New Features

-

Improvement

- Improve the VU Digital / VU Analogue (Display Options) performance.
- Fix the bug that the Display Off (Display Options) is invalid when power on the unit with 12V Trig In.
-

Additional information

Firmware update instructions.
1. Turn off the power supply to the device (rear panel mains switch)
2. Install the update file on a FAT32 formatted USB drive (maximum 32GB, folder name must be '9000A' and contents should 9000A.bin)
3. Insert the USB drive to the 'UPDATE' USB socket on the rear panel of the device.
4. Push and hold front panel standby button.
5. Turn on the power supply to the device (rear panel mains switch) while continuing to hold the standby button.
6. Release the standby button and the display will show 'upgrade processing'.
7. Allow the device to apply the software update. This may take a few minutes.
8. When update is complete, the device is ready to use.

Change history

V1.76
1.Improve DLL settings logic and function

V1.75

1. Improve DPLL setting to save change immediately.

V1.72
1. Improve interaction of knobs or remote control keys' detection in auto standby function.
2. Optimize Bluetooth track information refresh after change source.
3. Improve backlight brightness

V1.68
First release version